



NOTE:

1. POLES MAY BE WOOD, CONCRETE OR METAL.
2. INSULATORS ARE ANGLED DOWNWARD TO PREVENT NESTING / PERCHING. BY PREDATORY BIRDS.
3. SPIKES ARE INSTALLED AT TOP OF POLE TO PREVENT NESTING / PERCHING. BY PREDATORY BIRDS.

Source: Black and Veatch (1999).

Figure 4-26